

VISUAL TANK INSPECTION REPORT

Vessel :
Port/Terminal:
Product/Cargo:

ETT-112

Hercules Shipyard / Freeport, Texas

Your Reference:

Our Reference: FP/97-5220

Normal Butanol

Date : April 21, 1997

Tank			
Number	1C	2C	3C
Tank			
Coating	Mild Steel	<u> </u>	Mild Steel
Last			
Cargo	Cyclohexane	Cyclohexane	Cyclohexane
Second Last			
Cargo	Cyclohexane	Cyclohexane	Cyclohexane
Third Last			
Cargo	Cyclohexane	Cyclohexane	Cyclohexane
Visual Cleanliness			
Accepted *	<u>Accepted</u>	<u>Accepted</u>	Accepted
isual Cleanliness	•		
Rejected *			
Pime/Date	1910	1910	1910
Inspected	04/21/97	04/21/97	04/21/97

Method said to have been used to clean tanks: Tanks #1 Center, #2 Center, #3 Center and Lines: Stripped and blown dry.

Information regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be guaranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper information supplied. This report, of necessity, is based on such information.

* The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.

I T S-Caleb Brett